

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CU484
SW
1/2-1
0.756 mi.
3991 ft.

VAULT #5747
W 24TH ST/SURF AVE
BROOKLYN, NY

NY Spills S103829530
N/A

Site 3 of 7 in cluster CU

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: VAULT #5747
Address: W 24TH ST/SURF AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9815441 / 1999-04-14
Facility ID: 9815441
Facility Type: ER
DER Facility ID: 185156
Site ID: 224009
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-03-29
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-03-29
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-03-29
Spill Record Last Update: 2000-06-19
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN

Spiller Company: 999
Contact Name: STEVE ROMERO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS NOTES Undiaperable sheen of oil found on 350 gals. of water in V5747. Contained. No sewers or waterways affected. sample taken on a 4-6 hr. turnaround, unit pressure tested, ok. Tag #08247 placed. Crew sent to locaton for transformer removal. 3-30-99 18:42 Flush OPS reports cleanup complete and tag removed. Incident Closed."

Remarks: "MATERIAL CONTAINED IN MANHOLE IN VAULT-PENDING TEST RESULTS CLEANUP WILL TAKE PLACE-CON ED #123926"

All Materials:

Site ID: 224009
Operable Unit ID: 1073455
Operable Unit: 01
Material ID: 308547
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: .00
Oxygenate: Not reported